ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura
Street ID	**Street Name**	**Significant Landmark**
W0417, W0320, W0324	NA, Chikkanna Lyt 1st Crs, R H B Colcny, 3rd Crs	Munigurappa Layout
Segment No.	**Total Length (m)**	
7/C-W0417/S120419	267.47	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	173.00	77.601079	13.066647	77.602667	13.066498	Main Road	Dead End
2	94.47	77.601801	13.066869	77.602670	13.066811	1st Cross	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to drains cross roads of munigurappa layout in amruthahalli in ward no.07 Byataranapura.	2500000	2019-20
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Tender	1.Construction of RCC Drains In 1st Cross.2.Providing and laying Granite Stone Slabs.3.Providing and laying Kerb Stones in 1st, 2nd and 3rd Cross.4.Desilting of drains in 2nd and 3rd Cross.	007-20-000090
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/74/20-21	13/08/2020	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
10/11/2020	09/11/2023	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s Sri Channakeshawa Enterprises, Sri Kiran Gowda D		0.00
Phone No.	**E-Mail ID**	

8660318348

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Pushpalatha.N.D
Date of Inspection	**Remarks**	
11/11/2020		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0417, W0320, W0324

esignation	Approver Name	Date	Target Date	Remark
CE	Sri.S.P.Ranganath	11/11/2020	11/12/2020	As proposed
SE	Vijay Kumar Haridas	11/11/2020	11/12/2020	Forwarded
EE	Mohandas H T	11/11/2020	11/12/2020	verified
AEE	G Srinivasa Murthy	11/11/2020	11/12/2020	Verified
AE	Pushpalatha N D	11/11/2020	11/12/2020	Mobile Verification Done
AE	Pushpalatha N D	11/11/2020	11/12/2020	Forwarded

Assistant Executive Engineer
Kodigehalli Sub Division
Bruhat Bangalore Mahanagara Palike
Bangalore - 560 092

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0417, W0320, W0324